

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

FIG. 1







FIG. 2



**FIG. 3**

**FIG. 4**



- 17: ELASTOMER (SECOND ELASTIC MATERIAL)
- 18: PUSHER (PUSHING MEMBER)
- 20: THIN FILM PROBE (FIRST SHEET)
- 24: CONTACT TERMINAL
- 27: REINFORCING MATERIAL (FIRST REINFORCING MEMBER)
- 28: GROOVE
- 29: ELASTOMER (FIRST ELASTIC MATERIAL)
- 30: PUSHING MECHANISM


**FIG. 5**

FIG. 6




FIG. 7









FIG. 8




**FIG. 9**





**FIG. 10**






**FIG. 11**





**FIG. 12****FIG. 13**


**FIG. 14**




**FIG. 15****FIG. 16**


**FIG. 17**


**FIG. 18**


*FIG. 19*





*FIG. 20*


*FIG. 21*

*FIG. 22*


*FIG. 23*

*FIG. 24*



**FIG. 26**

**FIG. 27**



**FIG. 28**

